




SAFETY CERTIFICATE

This is to certify, that the School Building of St. Luke's School, Burla has been inspected by the Asst. Executive Engineer, Burla(R&B) Sub-Division, Burla and Assistant Engineer, Burla(R&B) Section, Burla on Dt. 09.11.2022 and reported the school building is structurally safe. This is for favour of your kind information and necessary action.

This certificate is valid up to Dt. 09.11.2023.


Assistant Engineer
Burla(R&B) Section, Burla


Asst. Executive Engineer,
Burla(R&B) Sub-Division,
Burla(R&B) Sub-Division, Burla


MANAGER,
St. Luke's School, Burla
Opp. Ram Vihar, P.O. Jagruti Vihar
Dist. Sambalpur-768020, Odisha


PRINCIPAL,
St. Luke's School, Burla
Opp. Ram Vihar, P.O. Jagruti Vihar
Dist. Sambalpur-768020, Odisha